

बिहार सरकार  
ग्रामीण विकास विभाग

संकल्प

पटना, दिनांक-...२५/०५/२०२५

विषय: स्वर्ण जयंती ग्राम स्वरोजगार योजना के अंतर्गत विशेष परियोजना के तहत स्वीकृत टी-प्रोसेसिंग एण्ड पैकेजिंग इकाई, कालिदास किस्मत, पोठिया की भूमि, प्लांट एवं मशीनों को बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति संपोषित प्रोड्यूसर कंपनी के माध्यम से केवल परिचालन हेतु बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति को हस्तांतरित करने तथा फैक्ट्री के परिचालन हेतु संबंधित प्रोड्यूसर कंपनी के साथ समझौता ज्ञापन करने का अधिकार प्रदत्त करने के संबंध में ।

वर्ष 2002 में स्वर्ण जयंती ग्राम स्वरोजगार योजना के अंतर्गत विशेष परियोजना के तहत किशनगंज जिले में टी-प्रोसेसिंग एण्ड पैकेजिंग इकाई की स्थापना की गई। इस इकाई का परियोजना व्यय 9.64 करोड़ रुपए निर्धारित था। मूल संकल्पना यह थी कि इस इकाई का परिचालन फेडरेशन ऑफ सेल्फ हेल्प ग्रुप के माध्यम से किया जाएगा। इस विशेष परियोजना के तहत मौजा कालिदास किस्मत थाना न0-100 में कुल 10.60 एकड़ भूमि का क्रय किया गया । इस भूमि पर टी प्रोसेसिंग प्लांट हेतु कतिपय भवनों का निर्माण किया गया तथा परिचालन हेतु मशीनों एवं अन्य आवश्यक सामग्रियों का क्रय किया गया जिसका विवरण क्रमशः परिशिष्ट-क (भूमि विवरण), परिशिष्ट-ख (संरचनाएँ) एवं परिशिष्ट-ग (प्लांट एवं मशीनरी) के रूप में संकल्प के साथ संलग्न किया गया है।

2. उक्त परियोजना में प्लांट मशीनों का अधिष्ठापन वर्ष 2015 तक हो चुका था किन्तु सक्षम फेडरेशन का गठन नहीं हो पाने के कारण अस्थाई व्यवस्था के तहत इसका परिचालन निविदा के आधार पर दिनांक-29.04.2015 के प्रभाव से 10 वर्षों के लिए M/s संचेती टी कंपनी, एस०एफ० रोड, जलपाई मोड़, सिलीगुड़ी-734405 को सौंपा गया। यह अवधि दिनांक-28.04.2025 को समाप्त हो जाएगी।

3. सम्प्रति परियोजना की मूल अवधारणा के अनुसार बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति संपोषित प्रोड्यूसर कंपनी का गठन किया जा चुका है। स्थानीय चाय उत्पादक पत्नी तोड़ने वाली महिलाएं इस कंपनी की अंशधारक बनी हैं। कंपनी में अनुभवी पेशेवर कार्यरत हैं तथा टी बोर्ड ऑफ इंडिया, सिलीगुड़ी के द्वारा कंपनी को तकनीकी सहयोग प्राप्त करने हेतु बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति, पटना द्वारा दिनांक 14.03.2023 को एक एकरारनामा भी किया गया है। टी प्रोसेसिंग, पैकेजिंग एवं उसके मार्केटिंग से प्रत्यक्षतः संबद्ध होने से बिहार ग्रामीण



जीविकोपार्जन प्रोत्साहन समिति से जुड़े कृषक उद्यमियों के उद्यमशीलता में वृद्धि होगी तथा इसके लाभ का अधिकतम प्रतिफल उन्हें मिलेगा।

4. जिला पदाधिकारी, किशनगंज के पत्रांक 137 दिनांक 28-01-2025 से उक्त प्रोसेसिंग इकाई को संचालन हेतु बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति को हस्तांतरित करने के संबंध में अनुरोध किया गया है।

5. सम्प्रति स्वर्ण जयंती ग्राम स्वरोजगार योजना अंतर्गत विशेष परियोजना के तहत स्थापित टी प्रोसेसिंग एवं पैकेजिंग इकाई को अपने अधिष्ठापन की मूल अवधारणा के अनुसार मात्र परिचालन हेतु बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति को हस्तांतरित किया जाना समुचित प्रतीत होता है। भूमि एवं सृजित परिसम्पत्तियों पर ग्रामीण विकास विभाग का पूर्ववत स्वामित्व बना रहेगा।

6. उपरोक्त के आलोक में स्वर्ण जयंती ग्राम स्वरोजगार योजना के अंतर्गत विशेष परियोजना के तहत स्वीकृत टी-प्रोसेसिंग एण्ड पैकेजिंग इकाई, कालिदास किस्मत, पोठिया की भूमि, प्लांट एवं मशीनों को बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति संपोषित प्रोड्यूसर कंपनी के माध्यम से केवल परिचालन हेतु बिहार ग्रामीण जीविकोपार्जन प्रोत्साहन समिति को हस्तांतरित करने तथा फैक्ट्री के परिचालन हेतु संबंधित प्रोड्यूसर कंपनी के साथ समझौता ज्ञापन करने का अधिकार प्रदत्त किये जाने की स्वीकृति प्रदान की जाती है।

7. इस पर दिनांक-25.04.2025 को हुई राज्य मंत्रिपरिषद् की बैठक में मद सं0-08 के अंतर्गत स्वीकृति प्राप्त है।

अनुलग्नक-यथोक्त।

आदेश:- आदेश दिया जाता है कि इस संकल्प को बिहार राज पत्र के असाधारण अंक में प्रकाशित किया जाय एवं इसकी प्रतिलिपि सरकार के सभी विभागों एवं महालेखाकार, बिहार, पटना को सूचनार्थ भेजी जाय।

बिहार राज्यपाल के आदेश से

(लोकेश कुमार सिंह)

सरकार के सचिव

जापांक 4002533 /

पटना, दिनांक- 25/04/2025

प्रतिलिपि- ई-गजट कोषांग, वित्त विभाग, बिहार, पटना को सी.डी. सहित बिहार राजपत्र के आगामी असाधारण अंक में प्रकाशनार्थ प्रेषित।

अनुरोध है कि प्रकाशित राजपत्र की 100 मुद्रित प्रतियाँ इस विभाग को भी उपलब्ध करायी जाय।

सरकार के सचिव

ज्ञापांक 4002533 /

पटना, दिनांक- 25/04/2025

प्रतिलिपि- महालेखाकार, बिहार, वीरचन्द पटेल पथ, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु प्रेषित ।

सरकार के सचिव

ज्ञापांक 4002533 /

पटना, दिनांक- 25/04/2025

प्रतिलिपि- राज्यपाल के प्रधान सचिव/ मुख्यमंत्री के प्रधान सचिव/मंत्री, ग्रामीण विकास विभाग के आप्त सचिव/ मुख्य सचिव/ विकास आयुक्त/अध्यक्ष-सह-सदस्य, राजस्व परिषद, बिहार/सभी अपर मुख्य सचिव/प्रधान सचिव/सचिव/सभी विभागाध्यक्ष/ सभी प्रमंडलीय आयुक्त/सभी जिला पदाधिकारी/सभी उप विकास आयुक्त को सूचनार्थ एवं आवश्यक कार्रवाई हेतु प्रेषित ।

सरकार के सचिव

ज्ञापांक- 4002533 /

पटना, दिनांक- 25/04/2025

प्रतिलिपि- मुख्य कार्यपालक पदाधिकारी, जीविका/ वित्त विभाग, बजट शाखा/ योजना एवं विकास विभाग/बजट शाखा, ग्रामीण विकास विभाग/सभी कोषागार पदाधिकारी/सभी उप कोषागार पदाधिकारी/सभी पदाधिकारी, ग्रामीण विकास विभाग को सूचनार्थ एवं आवश्यक कार्रवाई हेतु प्रेषित।

सरकार के सचिव

ज्ञापांक 4002533 /

पटना, दिनांक- 25/04/2025

प्रतिलिपि- आईओटीओमैनेजर, ग्रामीण विकास विभाग को विभागीय वेबसाईट पर अपलोड करने हेतु सूचनार्थ प्रेषित ।

सरकार के सचिव

## SCHEDULE "A" (Details of Land &amp; Building)

## I. Land Details

अंचल-पोठिया, थाना-पोठिया, जिला-किसानगंज के तहत निर्गत अगिधारी नामांतरण शुद्धिपत्र के अनुसार  
टी-प्रोसेसिंग एण्ड पैकेजिंग इकाई, कालीदास किस्मत, पोठिया में सन्निहित भूमि का व्यौरा

| मोजा           | थाना नं० | खाता नं० | खेसरा नं० | रकबा      |
|----------------|----------|----------|-----------|-----------|
| कालीदास किस्मत | 100      | 10       | 1837      | 0.88      |
|                |          | 23       | 1835      | 0.14      |
|                |          | 25       | 1825      | 0.15      |
|                |          | 52       | 1831      | 0.65      |
|                |          | 79       | 1823      | 0.05      |
|                |          | 79       | 1826      | 0.41      |
|                |          | 79       | 1834      | 0.15      |
|                |          | 81       | 1817      | 0.10      |
|                |          | 83       | 1818      | 0.32      |
|                |          | 83       | 1822      | 0.45      |
|                |          | 83       | 1838      | 0.78      |
|                |          | 86       | 1740      | 0.07      |
|                |          | 86       | 2516      | 0.02      |
|                |          | 86       | 1819      | 0.48      |
|                |          | 86       | 1827      | 1.11.5    |
|                |          | 180      | 1815      | 0.02      |
|                |          | 108      | 1828      | 1.01      |
|                |          | 132      | 1816      | 0.34      |
|                |          | 132      | 1833      | 1.14      |
|                |          | 146      | 1829      | 1.33      |
|                |          | 166      | 1830      | 0.10      |
|                |          | 170      | 1832      | 0.50      |
|                |          | 199      | 1836      | 0.08      |
|                |          | 199      | 1824      | 0.18      |
|                |          |          |           | 10.60 1/2 |

(Sanjay Kumar)  
Circle Officer, Pothia

(B. K. Mishra)  
Additional Collector, Kishanganj



SCHEDULE "A" (Details of Land & Building)

II. Details Of Building As Per Physical Verification On 28.4.2015 At Tea Processing & Packaging Unit, Kalidas, Kismat, Pothia

Details of Building

1. Weigh Bridge Room
2. Four Staff Quarters
3. One Dining Room for Mess Purpose & Creche
4. One Generator Room
5. One CTC Room
6. One Workshop
7. One Dryer Room
8. One Sorting Room
9. One Packaging Room
10. One Manager Bungalow
11. One Assistant Manager Bungalow
12. One Under Construction Room
13. One Guard Room

*Sampatmal Sancheti*  
(Sampatmal Sancheti)  
Proprietor, Sancheti Tea Company

*Rajeev Baid*  
(Rajeev Baid)  
Representative-Sancheti Tea Co.

28/4/2015


*Rajkumar Sharma*  
(Rajkumar Sharma)  
G.M.DIC-Kishanganj

*Sanjay Kumar*  
(Sanjay Kumar)  
Circle Officer-Pothia

*Suman Chakraborty*  
(Suman Chakraborty)  
FAO-Tea Board, India

13/4/2015

*Bharat Bhushan Prasad*  
(Bharat Bhushan Prasad)  
Director, Accounts, DRDA, Kishanganj



परिशिष्ट - 1

144

**SCHEDULE 'B' ( LIST OF PLANT & MACHINERY)**  
**LIST & DESCRIPTION OF MACHINERIES/OTHER ASSETS FOUND IN TEA PROCESSING &**  
**PACKAGING UNIT, KALIDASS KISMAT, POTHIA, DURING PHYSICAL VERIFICATION ON**  
**28.4.2015 BY TECHNICAL TEAM CONSTITUTED BY DISTRICT MAGISTRATE, KISHANGANJ VIDE**  
**LETTER NO.545/DRDA DATED 28.4.15.**

| S.N | Name of Machine/Asset                                                           | Location                            | Condition                                                                                                                           | Annexure        |
|-----|---------------------------------------------------------------------------------|-------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|-----------------|
| 1   | 16 Nos. Withering Trough                                                        | Before Rolling Room (CTC Room)      | Damage all Electrical Panel, Weld mesh & netlon, missing Impeller blade of fan and motors                                           | 1               |
| 2   | Monorail                                                                        | Over the trough                     | Damaged drive arrangement & electrical component missing. All wheels are not in working condition.                                  | NA              |
| 3   | Hot Air Blower                                                                  | Near Withering Trough               | Damaged                                                                                                                             | NA              |
| 4   | 4 Nos. Rotor Vane                                                               | Starting of Rolling Room (CTC Room) | Panel board found damaged, Motor's vane some Resistors are missing and Iris Plate found damaged.                                    | 2               |
| 5   | 4 Bank CTC Machine & Ball breaker CTC machine & Cold Air Blowers found damaged. | After Rotor Vane                    | Electrical Panel Board damaged & Motor's electric Hoist with Roller lifting found missing.                                          | 3A, 3B, 3C & 3D |
| 6   | 4 Nos. Googhie                                                                  | After the CTC Machine               | Motors with pulley are missing, motor gear box with pulley are missing, electric connection, panel board & switches are damaged     | 4               |
| 7   | Conveyors                                                                       | After Googhie to CFM                | Motors with gear box and pulley are missing, electric connection & switches are damaged                                             | 5               |
| 8   | 4 Nos CFM                                                                       | After Conveyor                      | Motors with pulley are missing & electrical cable & panel Board found damaged, Mist Chamber " nozzle's pipe fitting, pump not found | 6               |
| 9   | 2 Nos. VFBD                                                                     | After Rolling Room                  | Motors with pulley & V-Belt missing & Panel board found damaged                                                                     | 7               |
| 10  | 2 Nos. Heater                                                                   | Attached with VFBD                  | Motors with pulley & V-Belt missing & Heater back side condition not ascertainable as fully enclosed.                               | NA              |

5/1/15

28/4/15

5/1/15

5/1/15

28/4/15

28/4/15

| S.N | Name of Machine/Asset                                       | Location                     | Condition                                                                                                                                                                                                                                                                                                                                                                                                     | Annexure |
|-----|-------------------------------------------------------------|------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| 11  | 2 Nos Chain Grate Stoker                                    | Attached with Heater         | Motor's Gear Box spocket, Pulley, V-Bell, Glutting door, steel rope with handle set found missing                                                                                                                                                                                                                                                                                                             | NA       |
| 12  | Sorting Room                                                | After VFBD Room              | Motors with pulley & V-Belt of sorting machine found missing & conveyor belt fully damaged                                                                                                                                                                                                                                                                                                                    | 8        |
| 13  | Work Shop Room                                              | Near Rolling Room            | Drive arrangement of milling & Grooving Chasing, TCG found missing & Motor not found.                                                                                                                                                                                                                                                                                                                         | 9        |
| 14  | Blower Room                                                 |                              | Net Open of Oil Heater, Gear pump with motor are missing. Blower motor guard, Electrical side damage and missing and all wiring are damaged, Heater Oil Pump are missing, Turf with motor with front net with starter are missing. MCB Panel damaged and all part are missing. 16 Nos. of Rotor Motor are missing, 3 Nos Gouge Motor are missing, 08 Nos Ventilator Register are missing. v-Belt are missing. | NA       |
| 15  | Engine Room (Power)                                         | Inside the factory left side | DG power 380 KVA (with canopy type & alternator) engine side damaged, battery, tapped cover, Radiator fan, blade, oil filter, diesel filter, back cover, AVR, dried plate, terminal box found missing.                                                                                                                                                                                                        | 10       |
| 16  | Engine Room (Power)                                         | Inside the factory left side | DG set 380 KVA (open type & Stamford alternator), Radiator, controlling box, back cover & winding found damaged, engine self, dynamo battery, fan, pulley, AVR & dryer set missing                                                                                                                                                                                                                            | 11       |
| 17  | Engine Room                                                 | Inside the factory left side | DG set 125 KVA (open type) engine, dynamo battery, fan, pump, electrical control box broken, wiring & battery, wiring, back cover, AVR, dryer terminal box & wire terminal missing. Radiator found damaged.                                                                                                                                                                                                   | 12       |
| 18  | Power House, All Machinery & Civil Electrical & Panel Board | Whole Factory                | All LT cables, incoming & out coming line are damaged. Distribution panel chamber damaged. All parts missing. Fuel pump for main tank to sub tank for engine room, motor, starter all missing. The panel board & the civil electrical line of the whole factory is damaged.                                                                                                                                   | NA       |

[illegible]

| S.N | Name of Machine/Asset                                 | Location                                               | Condition                                                                                                                                                                           | Annexure |
|-----|-------------------------------------------------------|--------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------|
| 19  | Transformer & OLTC                                    | Beside Engine Room                                     | 500 KVA Transformer cases are found but all internal parts & OLTC found missing                                                                                                     | NA       |
| 20  | Weigh Bridge                                          | Entrance of factory gate left side                     | Weighing scale & digital computer are missing. Weighing Plate damaged.                                                                                                              | NA       |
| 21  | Office building                                       | Left side of weighing bridge                           | All office equipment viz. furniture & fixtures, lighting, fans, computer's & necessary equipments of machines are missing                                                           | NA       |
| 22  | Manager's & Asst. Manager's bungalow & staff quarters | Inside the factory compound                            | Door and window found missing and building found in damaged condition                                                                                                               | NA       |
| 23  | Water Line & submerible pump                          | Inside the factory to supply water                     | Water Line fully damaged and is not in working condition. Submersible pump & some water tank are missing. All the sanitary & bath fittings missing from the whole factory premises. | NA       |
| 24  | Ventilation & window glass of processing Room         | Rolling Room, Work Shop Room, Sorting Room, Dryer Room | Glass Door and Window are found broken                                                                                                                                              | NA       |
| 25  | Lighting system of complete factory & quarters        | Factory Premises                                       | Complete lighting system found damaged but 75 nos. of tubelight fittings found.                                                                                                     | NA       |
| 26  | Boundary                                              | Around the factory                                     | Safety wiring on wall fully damaged                                                                                                                                                 | NA       |
| 27  | Main Gates                                            | Both sides                                             | Painting to be done.                                                                                                                                                                | NA       |
| 28  | Spot Humidifier in CFM Room                           | CFM                                                    | 10 nos. found                                                                                                                                                                       | NA       |
| 29  | Exhaust Fans                                          | Factory Premises                                       | 10 nos. found                                                                                                                                                                       | NA       |
| 30  | Storgae blns with de-humidifier                       | Sorting Room                                           | Found                                                                                                                                                                               | NA       |
| 31  | Vibro Screen Sorter                                   | Sorting Room                                           | 4 nos. found                                                                                                                                                                        | NA       |
| 32  | Sorting Machine                                       | Sorting Room                                           | 7 nos. found                                                                                                                                                                        | NA       |
| 33  | CTC Rollers                                           | Workshop                                               | 16 sets of 13.5" rollers available spare                                                                                                                                            | NA       |

(Sampatmal Sancheti)  
Proprietor, Sancheti Tea Company

(Rajkumar Sharma)  
G.M.DIC-Kishanganj

(Rajeev Baid)  
Representative-Sancheti Tea Co.

(Sanjay Kumar)  
Circle Officer-Pothia

(Suman Chakraborty)  
FAO-Tea Board, India

(Bharat Bhushan Prasad)  
Director, Accounts, DRDA, Kishanganj