

बिहार सरकार  
जल संसाधन विभाग

**आदेश**

Dam Safety Act, 2021 के Section 38 के अनुसार राज्य अंतर्गत सभी निर्दिष्ट बाँधों का Independent Panel of experts के द्वारा पाँच सालों में Comprehensive Dam Safety Evaluation किये जाने का प्रावधान है।

2. निदेशानुसार बिहार राज्य के निर्दिष्ट बाँधों की सुरक्षा के दृष्टिकोण से उनका निरीक्षण कर उनकी त्रुटियों तथा निराकरण संबंधी सुझाव प्रदान करने हेतु Regulation के अनुसार पूर्व में गठित DSRP-I, II & III के सदस्यों में संशोधन कर तीन नए Dam Safety Review Panel यथा DSRP-I, DSRP-II तथा DSRP-III का पुर्नगठन निम्नरूपेण किया जाता है :-

**DSRP-I**

Sl. No.	Name of the Members	Domain/ Expertisation	Designation in DSRP	Address & Contact Details
1.	Shri A.K. Bajaj	Hydro-Mechanical Expert	CHAIRMAN	A-167, Defence Colony, 3 <sup>rd</sup> Floor, New Delhi - 110024 (Ph-9810105280, email-akbajaj@gmail.com)
2.	Shri Rajeev Sachdeva	Dam Safety Expert	Member	F-184, Upper Ground Floor, Man Sarovar Garden, New Delhi-110015 (Ph-9596890077/9958930077, email-sachdevarajeev@gmail.com)
3.	Dr. Sharad Govind Joshi	Construction Supervision Expert / Design Expert	Member	#160, Shreesh, 3 <sup>rd</sup> Cross, 3 <sup>rd</sup> Main, Siddeshwar Park, Vidyanagar Hubli, Karnataka-580031 (Ph-9538881948, email-gsharadjoshi@gmail.com)
4.	Shri Mandapalli Raju	Geologist	Member	F101, Sandhyagiri apt., Kalyan Nagar, Dilsukh Nagar, Hyderabad-0500060 (Ph-9432672087, email-geolraju@gmail.com)
5.	Shri Saran Aadhar	Hydrologist	Member	Office 114, Department of Civil & Infrastructure Engineering, IIT Jodhpur, Jodhpur-Rajasthan-342030 (Ph-9009671041, email-saran.aadhar@iitj.ac.in)
6.	Shri D. Srinagesh	Seismic Expert	Member	16-9-831/7/1, Sarojini Nagar Colony, Old Malakpet, Hyderabad-500036 (Ph-9440289075, email-seismosrinagesh@gmail.com)
7.	Shri Rajesh Kumar Srivastava	Instrumentation Expert	Member	174, Mayur Nagar, Gwalior, MP-474011 (Ph-9406501107, email-gwaliorrajesh@gmail.com)

## DSRP-II

Sl. No.	Name of the Members	Domain /Expertisation	Designation in DSRP	Address & Contact Details
1.	<b>Shri J. Chandra Shekhar Iyer</b>	Dam Safety Expert	CHAIRMAN	B-57, Vrindavan Apartment, Plot-1, Sector-6, Dwarka, New Delhi-110075 (Ph-9868916826, email-jchandra69@gmail.com)
2.	Shri K. Satyanarayana	Hydro-Mechanical Expert	Member	1-7-181,181/A Susmi Enclave Flat no.-202, Bakaram, Musheerabad, Hyderabad Telangana-500020 (Ph-9440817279/7207639459, email-satyamech8@gmail.com)
3.	Dr. Sharad Govind Joshi	Construction Supervision Expert/ Design Expert	Member	#160, Shreesh, 3 <sup>rd</sup> Cross, 3 <sup>rd</sup> Main, Siddeshwar Park, Vidyanagar Hubli, Karnataka-580031 (Ph-9538881948, email-gsharadjoshi@gmail.com)
4.	Shri Rakesh Chandra Sharma	Geologist	Member	C 101, Jal Vihar Welfare Society, Near KJ Greens, Sector - 77, Faridabad, Haryana - 121004, (Ph-9971859393, email-rcsharma_geologist@rediffmail.com)
5.	Shri Rajendra Chalisgaonkar	Hydrologist	Member	Flat No. 1201, Harmony Sky Suites, Ghodbunder Road, Owale, Thane (West)-400615 (Ph-9411175149, email-chalisgaonkar@gmail.com)
6.	Shri Naveen Kumar Jain	Seismic Expert	Member	34, Sitaram Apartment, 102 I.P. Extension, Patparganj, Delhi-110092 (Ph-9650992072, email-nkj_99@hotmail.com)
7.	Shri Mahabir Dixit	Instrumentation Expert	Member	A1001 Ramkrishan Cghs Plot No 12 Sector 23 Dwarka New Delhi-110077 (Ph-9871747490, email-MDIXIT64@GMAIL.COM)

## DSRP-III

Sl. No.	Name of the Members	Domain/Expertisation	Designation in DSRP	Address & Contact Details
1.	<b>Shri Shailesh Kumar Srivastava</b>	Design Expert	CHAIRMAN	A-58, Vrindavan Apartment, Plot-1, Sector-6, Dwarka, New Delhi-110075 (Ph-8380072764, email-cwc.srivastava@gmail.com)
2.	Shri Rajeev Kumar	Construction Supervision Expert	Member	2524, Fourth Floor, Sector- 57, Gurgaon-122003 (Ph-9968312991, email-rajolly5@iitdalumni.com)
3.	Shri Rajeev Sachdeva	Dam Safety Expert	Member	F-184, Upper Ground Floor, Man Sarovar Garden, New Delhi-110015 (Ph-9596890077/9958930077, email-sachdevarajeev@gmail.com)

4.	Shri Gulshan Raj	Hydro-Mechanical Expert	Member	H.No-1180, C-1, Vasant Kung, New Delhi-110070 (Ph-9999277474, email-gulshanraj1964@yahoo.co.in)
5.	Shri Shyam Lal Kapil	Geologist	Member	Flat no.68,Sadhbhawna Apartment plot no. 13 IP Extension New Delhi-110092 (Ph-9911103790, email-shyamkapil@gmail.com)
6.	Shri Rajendra Chalisgaonkar	Hydrologist	Member	Flat No. 1201, Harmony Sky Suites, Ghodbunder Road, Owale, Thane (West)-400615 (Ph-9411175149, email-chalisgaonkar@gmail.com)
7.	Shri Naveen Kumar Jain	Seismic Expert/ Instrumentation Expert	Member	34, Sitaram Apartment, 102 I.P. Extension, Patparganj, Delhi-110092 (Ph-9650992072, email-nkj_99@hotmail.com)

उक्त पर प्रधान सचिव, जल संसाधन विभाग, पटना का अनुमोदन प्राप्त है।

विश्वासभाजन

ह0/-

(आलोक कुमार)

संयुक्त सचिव (अभियंत्रण)

ज्ञापांक- रा0बाँ0सु0सं0/कार्य-03/2026(भाग-IV)

पटना, दिनांक :- / /2026

प्रतिलिपि:- अध्यक्ष, राज्य बाँध सुरक्षा समिति, पटना -सह- अभियंता प्रमुख, सिंचाई सृजन जल संसाधन विभाग, पटना/अभियंता प्रमुख, मुख्यालय, जल संसाधन विभाग, पटना/अभियंता प्रमुख, बाढ़ नियंत्रण एवं जल निस्सरण, जल संसाधन विभाग, पटना/मुख्य अभियंता, योजना एवं मोनिटरिंग, जल संसाधन विभाग, पटना/प्रभारी प्रमुख, राज्य बाँध सुरक्षा संगठन, पटना को सूचनार्थ एवं आवश्यक कार्रवाई हेतु प्रेषित।

ह0/-


(आलोक कुमार)

संयुक्त सचिव (अभियंत्रण)

ज्ञापांक- रा0बाँ0सु0सं0/कार्य-03/2026(भाग-IV) 331

पटना, दिनांक :- 29/04/2026

प्रतिलिपि:- कार्यपालक अभियंता, आई0टी0, सूचना एवं प्रावैधिकी केन्द्र, जल संसाधन विभाग, पटना को ई-मेल करने तथा वेबसाईट पर अपलोड करने हेतु प्रेषित।

  
(आलोक कुमार)

संयुक्त सचिव (अभियंत्रण)